

1

Initially, a first plasticized material is injected into an injection mold and, once this material has hardened on the edge, a second plasticized material is injected into the injection mold and only the second plasticized material is moved during solidification. In this manner, an increased strength of the injection molded part is realized.

7